

外装状態			
キャブコーション	フレーム番号	フレームのさび	飛石
有	確認済	小	点傷有

エンジン		
点検項目	結果	状態
異音	◎	
オイル混入	◎	
オイル漏れ	○	ロッカカバーオイルしみ跡
水混入	◎	
水漏れ	◎	
燃料漏れ	◎	
排気	◎	
マフラー	◎	
ターボ	◎	
冷却水吹返	◎	
ミッション		
点検項目	結果	状態
ギア鳴き	◎	
ギア抜け	◎	
クラッチ	◎	
異音	◎	
オイル漏れ	◎	
リターダ	◎	永久磁石式

電装関係		
点検項目	結果	状態
エアコン	◎	
スターター	◎	
オルタネーター	◎	
P/W（運転席）	◎	
P/W（助手席）	◎	
坂道発進装置	◎	
異常ランプ	◎	
オーディオ	◎	
バックカメラ	◎	カラー
電格ミラー	◎	
ETC	◎	標準
タコグラフ	◎	アナログ
上物仕様		
点検項目	結果	状態
床材質	/	木材

キャビン		
点検項目	結果	状態
シート	○	破れ、へたり、擦れ、汚れ
ヘッドライト	◎	HID
ウィンカー	◎	
ワイパー	△	ワイパーゴム切れ
ミラー	◎	
走行関係		
点検項目	結果	状態
リーフサス	◎	
エアサス	◎	リアエアサス
パワステ	◎	
ハンドル	○	擦れ
燃料タンク	◎	スチール 300L 200L
デフ		
点検項目	結果	状態
異音	◎	
オイル漏れ	◎	
デフロック	◎	

記録簿 無○

Technical drawings of a truck body showing front and side views with dimensions.

Front View (Left): Shows the front of the truck body. Dimensions include a total width of 2400mm and a height of 1200mm. The front panel is divided into two sections, each labeled "外装キズ" (Exterior Damage).

Side View (Right): Shows the side profile of the truck body. Dimensions include a total length of 6000mm and a height of 1200mm. The side panel is labeled "外装へこみ" (Exterior Dents).

外装 キズ	外装 へこみ	うき	曲がり	サビ	補修跡	割れ	庫内 キズ	庫内 へこみ	庫内 穴あき	床 汚れ
----------	-----------	----	-----	----	-----	----	----------	-----------	-----------	---------