

管理番号：0737009

外装状態			
キャブコーション	フレーム番号	フレームのさび	飛石
有	確認済	小	点傷有

Figure 1 shows the front and side views of a truck. The front view (left) labels damage on the windshield as '外装キズ' (Exterior Scratch) and on the bumper as '外装へこみ' (Exterior Dents). The side view (right) labels damage on the cab roof as '割れ' (Crack), on the side of the cab as '外装キズ' (Exterior Scratch), and on the side of the chassis as '外装キズ' (Exterior Scratch).

Figure 1 shows two line drawings of a truck on a blue grid background. The left drawing is a front view, and the right drawing is a side view. In the side view, three areas are labeled with black text: '外装キズ' (Exterior Damage) on the front fender, '補修跡' (Repair Mark) on the front bumper area, and '外装キズ' (Exterior Damage) on the side of the cab.

【外装】				【ボデー内】						
外装キズ	外装へこみ	うき	曲がり	サビ	補修跡	割れ	庫内キズ	庫内へこみ	庫内穴あき	床汚れ