

日付: R8.02/04

車両チェックシート

管理番号: 0238006

車 両 情 報						
車名	初年度登録	型式	形状	車台番号		
日野	令和5年01月	2KG-FD2ABG	アルミウィング	FD2AB-131901		
走行	馬力	シフト	ブレーキ	ボディ内寸		
94,823km	240PS／177KW	M/T 6速	エア－	長：6,270 mm	幅：2,400 mm	
				高：2,420 mm	門高：2,330 mm	

◎:良好 ○:通常走行問題なし △:要修理 /:装備無し ※あくまでも当社判断基準によるものです

[illegible]

ミッション			ハンドルの取付			燃料タンク		
点検項目	結果	状態	点検項目	結果	状態	点検項目	結果	状態
ギア鳴き	◎		タコグラフ	／		ハンドル	◎	
ギア抜け	◎					燃料タンク	◎	スチール 200L
クラッチ	◎		上物仕様					
異音	◎		点検項目	結果	状態	デフ		
オイル漏れ	◎		床材質	／	木材	点検項目	結果	状態
リターダ	／					異音	◎	
PTO	／					オイル漏れ	◎	
						デフロック	／	

特記事項	エンジンキー3本(メイン2、スベア1)、ボデーキー2本 キャブ内傷・汚れ有り バッテリーサイズ80D26L×2ヶ フロントガラス点傷多数モールギリギリにもあり 観音ドア左開閉硬い
記録簿	有 (R6/5～R7/7)

タイヤ残量				タイヤサイズ			
単位: mm							
	7	7		225/80R17.5	225/80R17.5		
	—	—		—	—		
9	9	9	9	225/80R17.5	225/80R17.5	225/80R17.5	225/80R17.5
—	—	—	—	—	—	—	—
スペア				スペア	225/80R17.5	—	
	13	—		素材: スチール	備考:		

上物仕様			
上物名	メーカー	型式「製造番号」	年式
アルミウイング	トランテックス	「W096J59」	令和4年
【備考】 ラッシングレール2段、引出しフック5対、LED車高灯3ヶ			
格納ゲート/ラジコン	トランテックス	「S2211006089」	令和4年11月
【備考】 全長1550mm、全幅2450mm、有効幅2320mm、ストッパー迄1400mm、庫内リモコン、ラジコン			
【備考】			

外装状態			
キャブコーション	フレーム番号	フレームのさび	飛石
有	確認済	無	点傷有

Figure 1 consists of two diagrams illustrating vehicle body parts and their corresponding parts list. The left diagram shows a car body with labels for '補修跡' (Repair mark), '外装キズ' (Exterior scratch), and 'うき' (Sill). The right diagram shows a truck body with labels for '外装キズ' (Exterior scratch), '庫内穴あき' (Interior hole), '外装へこみ' (Exterior dent), '床汚れ' (Floor stain), '庫内キズ' (Interior scratch), and '外装へこみ' (Exterior dent).

Figure 1 shows two diagrams of a vehicle, illustrating inspection points for damage. The left diagram is a front view, and the right diagram is a side view. Both diagrams are overlaid with a blue grid. Labels in Japanese indicate specific areas to inspect for damage.

Front View (Left):

- 外装キズ (Exterior Scratch/Damage) - Located on the hood, roof, and front bumper.
- 外装へこみ (Exterior Dents) - Located on the front fenders.
- サビ (Rust) - Located on the front bumper area.

Side View (Right):

- 外装キズ (Exterior Scratch/Damage) - Located on the roof, rear window, and rear bumper.
- 庫内キズ (Interior Scratch/Damage) - Located on the side of the vehicle body.
- 外装へこみ (Exterior Dents) - Located on the rear fender.

【外装】

【ボデー内】

外装 キズ	外装 へこみ	うき	曲がり	サビ	補修跡	割れ	庫内 キズ	庫内 へこみ	庫内 穴あき	床 汚れ
----------	-----------	----	-----	----	-----	----	----------	-----------	-----------	---------