

管理番号：0737141

外装状態			
キャブコーション	フレーム番号	フレームのさび	飛石
有	確認済	小	点傷有

◎：良好 ○：通常走行問題なし △：要修理 ／：装備無し ※あくまでも当社判断基準によるものです

[illegible]

特記事項 *パートタイム4WD。キャブ内キズ汚れ。ルーフ傷。
エンジンキー2本（キーレス1本）。ボディキー2本。

記録簿 有 (R2/12~R4/11、R6/9、R6/11)

タイヤ残量	タイヤサイズ
単位: mm	
7 6	205/70R16 205/70R16
— —	— —
7 8 8 8	205/70R16 205/70R16 205/70R16 205/70R16
— — — —	— — — —
スベア 12 —	スベア 205/70R16 —
素材: スチール	備考:

【外装】

【ボデー内】

外装 キズ	外装 へこみ	うき	曲がり	サビ	補修跡	割れ	庫内 キズ	庫内 へこみ	庫内 穴あき	床 汚れ
----------	-----------	----	-----	----	-----	----	----------	-----------	-----------	---------