

上物仕様			
上物名	メーカー	型式「製造番号」	年式
平ボディ	メーカー完成車		平成30年
【備考】 煽り3方開 ロープフック：サイド6対/リヤ2ヶ所 ロープ穴3対 床フック5対 前後櫓増設 床板穴あき・浮き			

【備考】

【備考】			

ミッション			ETC			標準		
点検項目	結果	状態	タコグラフ	結果	状態	タコグラフ	結果	状態
ギア鳴き	◎							
ギア抜け	◎							
クラッチ	/							
異音	◎							
オイル漏れ	◎							
リターダ	/							

上物仕様			標準		
点検項目	結果	状態	タコグラフ	結果	状態
床材質	/	木材			

デフ			標準		
点検項目	結果	状態	エアサス	結果	状態
異音	◎		エアサス	/	
オイル漏れ	◎		パワステ	◎	
デフロック	/		ハンドル	○	擦れ
			燃料タンク	◎	スチール 80L

記録簿 有 (H31/1~R6/12)

Figure 1 consists of two diagrams of a vehicle on a blue grid background. The left diagram is a front view of a car, showing the hood, windshield, roof, and front bumper. Labels '外装キズ' (Exterior Damage) are placed on the left and right sides of the hood. The right diagram is a side view of the same car, showing the side profile, including the door, rear window, and rear wheel. Labels '外装キズ' (Exterior Damage) are placed on the front fender, rear door, and rear quarter panel. Labels '外装へこみ' (Exterior Dents) are placed on the front fender and the rear door.

Figure 1 consists of two diagrams illustrating the layout of a vehicle body. The left diagram shows a top-down view of a rectangular body with four '外装キズ' (Exterior Damage) labels. The right diagram shows a side profile view of a vehicle with four '外装キズ' labels along the roofline.

【ボデー内】

外装 キズ	外装 へこみ	うき	曲がり	サビ	補修跡	割れ	庫内 キズ	庫内 へこみ	庫内 穴あき	床 汚れ
----------	-----------	----	-----	----	-----	----	----------	-----------	-----------	---------