

上物仕様			
上物名	メーカー	型式「製造番号」	年式
セルフローダー	キャリーラック		
【備考】＊コーションプレート無。スタンション穴14ヶ所。スタンション6本。後方床フック2ヶ。作業灯2ヶ（1ヶ不灯）。ウインチ付。ハイジャッキ。スロープハンガー。スロープ付。煽り曲り。ラジコン付（ウインチ・ハイジャッキ用）。			

【備考】

【備考】			

外装状態			
キャブコーション	フレーム番号	フレームのさび	飛石
有	確認済	小	点傷有




Diagram showing the front view of a truck cab. Labels indicate exterior damage: '外装キズ' (Exterior Damage) on the top left, '外装へこみ' (Exterior Dents) on the top right, and '外装キズ' (Exterior Damage) on the bottom center.




Diagram showing the side view of a truck cab. Labels indicate exterior damage: '外装' (Exterior) on the bottom left, '曲がり' (Bent) on the middle left, '外装キズ' (Exterior Damage) on the middle right, and 'サビ' (Rust) on the bottom right.

[illegible]

Figure 1 shows two line drawings of a truck on a blue grid. The left drawing is a front view, and the right drawing is a side view. The front view has a label '外装キズ' (Exterior Damage) on the front bumper. The side view has labels 'サビ' (Rust) on the front fender, '外装キズ' (Exterior Damage) on the front fender and rear door, '曲がり' (Bent) on the front fender and rear door, and '割れ' (Crack) on the rear door.

【ボデー内】

外装 キズ	外装 へこみ	うき	曲がり	サビ	補修跡	割れ	庫内 キズ	庫内 へこみ	庫内 穴あき	床 汚れ
----------	-----------	----	-----	----	-----	----	----------	-----------	-----------	---------